

Capital Needs Assessment

Villages At Bedford

Capital Needs Cost Summary

05/07/2023

ID: 435139

Performed By:

S Franco

Villages At Bedford: (Multiple Units) Capital Needs Cost Summary Capital Needs Assessment



Scheduled: 05/07/2023

Closed: May 11 2023

ID: 435139

Inspection Summary


<u>Total Units*</u>	<u>Inspected Units*</u>	<u>Unable to Inspect*</u>	<u>Units without Results*</u>
126	125	0	1
	<u>Occupied</u>	<u>Vacant</u>	<u>Offline</u>
	0	0	0
	<u>Recorded Cost*</u>	<u>Projected Cost*</u>	<u>Projected Cost per Unit*</u>
	\$66,672.00	\$67,205.38	\$533.38

Definition of Terms:

- *Total Units: Count of active units at the site
- *Inspected Units: Count of units with inspection results
- *Unable to Inspect: Count of Sampled Units that could not be entered
- *Recorded Cost: Total cost for all inspection results with a cost defined
- *Projected Cost: (Recorded Cost / Inspected Units) * Total Units
- *Projected Cost per Unit: Projected Cost / Total Units



Top Costs



Cost Summary - By Item

Item	Paint	Clean	Repair	Replace	Total
Bathtub/Shower	0 EA x \$0.0	0 EA x \$0.0	1 EA x \$515.00	0 EA x \$0.0	\$515.00
Door, Entry	0 EA x \$0.0	0 EA x \$0.0	20 EA x \$515.00	0 EA x \$0.0	\$10,300.00
Door, Interior	0 EA x \$0.0	0 EA x \$0.0	1 EA x \$103.00	0 EA x \$0.0	\$103.00
Erosion	0 SF x \$0.0	0 SF x \$0.0	22 SF x \$15.00	0 SF x \$0.0	\$330.00
Flooring	0 SF x \$0.0	0 SF x \$0.0	25 SF x \$3.00	0 SF x \$0.0	\$75.00
Lighting/Site	0 EA x \$0.0	0 EA x \$0.0	0 EA x \$0.0	1 EA x \$1,500.00	\$1,500.00
Paint	0 SF x \$0.0	0 SF x \$0.0	7845 SF x \$3.00	2600 SF x \$3.00	\$31,335.00
Refrigerator	0 EA x \$0.0	0 EA x \$0.0	0 EA x \$0.0	1 EA x \$721.00	\$721.00
Roofing, Asphalt Shingle	0 SF x \$0.0	0 SF x \$0.0	1190 SF x \$3.00	0 SF x \$0.0	\$3,570.00
Siding, Wood	0 SF x \$0.0	0 SF x \$0.0	1300 SF x \$9.00	0 SF x \$0.0	\$11,700.00
Sink and Faucet	0 EA x \$0.0	0 EA x \$0.0	1 EA x \$227.00	0 EA x \$0.0	\$227.00
Toilet	0 EA x \$0.0	0 EA x \$0.0	1 EA x \$206.00	0 EA x \$0.0	\$206.00
Well Pump	0 EA x \$0.0	0 EA x \$0.0	0 EA x \$0.0	1 EA x \$3,000.00	\$3,000.00
Window	0 EA x \$0.0	0 EA x \$0.0	0 EA x \$0.0	5 EA x \$618.00	\$3,090.00
				Villages At Bedford Total:	\$66,672.00

Cost Summary - by Area/Location

Unit Level

Bathroom 1

Item	Paint	Clean	Repair	Replace	Total
Bathtub/Shower	-	-	1 EA x \$515.00	-	\$515.00
Sink and Faucet	-	-	1 EA x \$227.00	-	\$227.00
Toilet	-	-	1 EA x \$206.00	-	\$206.00
Bathroom 1 Location Total:					\$948.00

Bedroom 1

Item	Paint	Clean	Repair	Replace	Total
Door, Interior	-	-	1 EA x \$103.00	-	\$103.00
Flooring	-	-	19 SF x \$3.00	-	\$57.00
Bedroom 1 Location Total:					\$160.00

Kitchen

Item	Paint	Clean	Repair	Replace	Total
Flooring	-	-	2 SF x \$3.00	-	\$6.00
Refrigerator	-	-	-	1 EA x \$721.00	\$721.00
Kitchen Location Total:					\$727.00

Living Area/Hallway

Item	Paint	Clean	Repair	Replace	Total
Door, Entry	-	-	18 EA x \$515.00	-	\$9,270.00
Flooring	-	-	4 SF x \$3.00	-	\$12.00
Living Area/Hallway Location Total:					\$9,282.00
Unit Level Total:					\$11,117.00

Cost Summary - by Area/Location (Continued)

Exterior Level

Entry Door

Item	Paint	Clean	Repair	Replace	Total
Door, Entry	-	-	2 EA x \$515.00	-	\$1,030.00
Entry Door Location Total:					\$1,030.00

Exterior Wall

Item	Paint	Clean	Repair	Replace	Total
Paint	-	-	7845 SF x \$3.00	2600 SF x \$3.00	\$31,335.00
Siding, Wood	-	-	1300 SF x \$9.00	-	\$11,700.00
Exterior Wall Location Total:					\$43,035.00

Rooftop

Item	Paint	Clean	Repair	Replace	Total
Roofing, Asphalt Shingle	-	-	1190 SF x \$3.00	-	\$3,570.00
Rooftop Location Total:					\$3,570.00

Windows

Item	Paint	Clean	Repair	Replace	Total
Window	-	-	-	5 EA x \$618.00	\$3,090.00
Windows Location Total:					\$3,090.00
Exterior Level Total:					\$50,725.00

Entire Site Level

Grounds

Item	Paint	Clean	Repair	Replace	Total
Erosion	-	-	22 SF x \$15.00	-	\$330.00
Lighting/Site	-	-	-	1 EA x \$1,500.00	\$1,500.00
Well Pump	-	-	-	1 EA x \$3,000.00	\$3,000.00
Grounds Location Total:					\$4,830.00
Entire Site Level Total:					\$4,830.00
Villages At Bedford Total:					\$66,672.00



Cost Summary - By Building/Unit

Building A

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	-	400 SF x \$3.00	\$1,200.00
Exterior Total:					\$1,200.00

Unit A-951

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit A-951 Total:					\$515.00
Building A Total:					\$1,715.00

Building B

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	-	500 SF x \$3.00	\$1,500.00
Exterior Total:					\$1,500.00
Building B Total:					\$1,500.00

Building C

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	-	1300 SF x \$3.00	\$3,900.00
Roofing, Asphalt Shingle (Rooftop)	-	-	250 SF x \$3.00	-	\$750.00
Exterior Total:					\$4,650.00

Unit C-969A

Item	Paint	Clean	Repair	Replace	Total
Sink and Faucet (Bathroom 1)	-	-	1 EA x \$227.00	-	\$227.00



Cost Summary - By Building/Unit (Continued)

Building C (Continued)

Unit C-969A (Continued)

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit C-969A Total:					\$742.00

Unit C-971A

Item	Paint	Clean	Repair	Replace	Total
Flooring (Bedroom 1)	-	-	2 SF x \$3.00	-	\$6.00
Unit C-971A Total:					\$6.00
Building C Total:					\$5,398.00

Building D

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	-	400 SF x \$3.00	\$1,200.00
Exterior Total:					\$1,200.00
Building D Total:					\$1,200.00

Building E

Unit E-995B

Item	Paint	Clean	Repair	Replace	Total
Toilet (Bathroom 1)	-	-	1 EA x \$206.00	-	\$206.00
Flooring (Bedroom 1)	-	-	1 SF x \$3.00	-	\$3.00
Unit E-995B Total:					\$209.00
Building E Total:					\$209.00



Cost Summary - By Building/Unit (Continued)

Building F

Exterior

Item	Paint	Clean	Repair	Replace	Total
Siding, Wood (Exterior Wall)	-	-	1300 SF x \$9.00	-	\$11,700.00
Exterior Total:					\$11,700.00

Unit F-946A

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit F-946A Total:					\$515.00

Unit F-948

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit F-948 Total:					\$515.00

Building F Total: \$12,730.00

Building G

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	240 SF x \$3.00	-	\$720.00
Roofing, Asphalt Shingle (Rooftop)	-	-	120 SF x \$3.00	-	\$360.00
Exterior Total:					\$1,080.00
Building G Total:					\$1,080.00

Building H

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	1 SF x \$3.00	-	\$3.00



Cost Summary - By Building/Unit (Continued)

Building H (Continued)

Exterior (Continued)

Item	Paint	Clean	Repair	Replace	Total
Roofing, Asphalt Shingle (Rooftop)	-	-	320 SF x \$3.00	-	\$960.00
Exterior Total:					\$963.00

Unit H-908A

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit H-908A Total:					\$515.00
Building H Total:					\$1,478.00

Building I

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	300 SF x \$3.00	-	\$900.00
Exterior Total:					\$900.00
Building I Total:					\$900.00

Building J

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	2300 SF x \$3.00	-	\$6,900.00
Window (Windows)	-	-	4 EA x \$618.00	-	\$2,472.00
Exterior Total:					\$9,372.00

Unit J-909A

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit J-909A Total:					\$515.00



Cost Summary - By Building/Unit (Continued)

Building J (Continued)

Unit J-911A

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit J-911A Total:					\$515.00

Unit J-913A

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit J-913A Total:					\$515.00

Unit J-915A

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit J-915A Total:					\$515.00
Building J Total:					\$11,432.00

Building K

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	1300 SF x \$3.00	-	\$3,900.00
Exterior Total:					\$3,900.00

Unit K-927A

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit K-927A Total:					\$515.00

Cost Summary - By Building/Unit (Continued)

Building K (Continued)

Unit K-927C

Item	Paint	Clean	Repair	Replace	Total
Flooring (Bedroom 1)	-	-	16 SF x \$3.00	-	\$48.00
Unit K-927C Total:					\$48.00
Building K Total:					\$4,463.00

Building L

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	400 SF x \$3.00	-	\$1,200.00
Window (Windows)	-	-	- 1 EA x \$618.00	-	\$618.00
Exterior Total:					\$1,818.00

Unit L-935A

Item	Paint	Clean	Repair	Replace	Total
Flooring (Living Area/Hallway)	-	-	2 SF x \$3.00	-	\$6.00
Unit L-935A Total:					\$6.00

Unit L-937A

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit L-937A Total:					\$515.00

Unit L-939A

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit L-939A Total:					\$515.00



Cost Summary - By Building/Unit (Continued)

Building L (Continued)

Unit L-941A

Item	Paint	Clean	Repair	Replace	Total
Flooring (Living Area/Hallway)	-	-	4 SF x \$3.00	-	\$12.00
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit L-941A Total:					\$527.00
Building L Total:					\$3,381.00

Building M

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	800 SF x \$3.00	-	\$2,400.00
Exterior Total:					\$2,400.00
Building M Total:					\$2,400.00

Building N

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	200 SF x \$3.00	-	\$600.00
Exterior Total:					\$600.00

Unit N-544

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit N-544 Total:					\$515.00
Building N Total:					\$1,115.00

Cost Summary - By Building/Unit (Continued)

Building O

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	2000 SF x \$3.00	-	\$6,000.00
Roofing, Asphalt Shingle (Rooftop)	-	-	300 SF x \$3.00	-	\$900.00
Exterior Total:					\$6,900.00

Unit O-518A

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit O-518A Total:					\$515.00

Unit O-522A

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit O-522A Total:					\$515.00

Unit O-524A

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit O-524A Total:					\$515.00

Unit O-524B

Item	Paint	Clean	Repair	Replace	Total
Door, Interior (Bedroom 1)	-	-	1 EA x \$103.00	-	\$103.00
Unit O-524B Total:					\$103.00

Unit O-534A

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Living Area/Hallway)	-	-	1 EA x \$515.00	-	\$515.00
Unit O-534A Total:					\$515.00

Cost Summary - By Building/Unit (Continued)

Building O (Continued)

Unit O-536B

Item	Paint	Clean	Repair	Replace	Total
Bathtub/Shower (Bathroom 1)	-	-	1 EA x \$515.00	-	\$515.00
Unit O-536B Total:					\$515.00
Building O Total:					\$9,578.00

Building P

Exterior

Item	Paint	Clean	Repair	Replace	Total
Door, Entry (Entry Door)	-	-	2 EA x \$515.00	-	\$1,030.00
Paint (Exterior Wall)	-	-	300 SF x \$3.00	-	\$900.00
Exterior Total:					\$1,930.00

Unit P-512

Item	Paint	Clean	Repair	Replace	Total
Refrigerator (Kitchen)	-	-	-	1 EA x \$721.00	\$721.00
Unit P-512 Total:					\$721.00
Building P Total:					\$2,651.00

Building Clubhouse

Exterior

Item	Paint	Clean	Repair	Replace	Total
Paint (Exterior Wall)	-	-	4 SF x \$3.00	-	\$12.00
Roofing, Asphalt Shingle (Rooftop)	-	-	200 SF x \$3.00	-	\$600.00
Exterior Total:					\$612.00
Building Clubhouse Total:					\$612.00



Cost Summary - By Building/Unit (Continued)

Site Level


Entire Site

Item	Paint	Clean	Repair	Replace	Total
Erosion (Grounds)	-	-	22 SF x \$15.00	-	\$330.00
Lighting/Site (Grounds)	-	-	- 1 EA x \$1,500.00		\$1,500.00
Well Pump (Grounds)	-	-	- 1 EA x \$3,000.00		\$3,000.00
				Entire Site Total:	\$4,830.00
				Site Level Total:	\$4,830.00
				Villages At Bedford Total:	\$66,672.00



Attribute Summary

Grounds: Remaining Life




Grounds: Age Range



Entry Door: Remaining Life




Entry Door: Door Size



Entry Door: Age Range




Exterior Wall: Remaining Life



Exterior Wall: Age Range




Rooftop: Remaining Life




Rooftop: Age Range




Windows: Remaining Life



Windows: Age Range




Electrical System: Remaining Life



Electrical System: Age Range




Fire Safety: Remaining Life



Fire Safety: Age Range




HVAC: Remaining Life



HVAC: Age Range




Bathroom 1: Remaining Life




Bathroom 1: Age Range




Bedroom 1: Age Range



Bedroom 1: Remaining Life




Dining Area: Remaining Life



Dining Area: Age Range



Kitchen: Remaining Life



Kitchen: Age Range




Kitchen: Appliance Make




Kitchen: Appliance Color




Laundry: Age Range




Laundry: Remaining Life




Living Area/Hallway: Remaining Life




Living Area/Hallway: Door Size




Living Area/Hallway: Age Range



Living Area/Hallway: Electric Panel Amps



Utility Closet: Remaining Life



Utility Closet: Age Range



Heat Map

Apt. Nbr.	Beds	Baths	HC	Sq. Ft.	Living Area/Hallway	Dining Area	Kitchen	Utility Closet	Bathroom (Half)	Bathroom 1	Bedroom 1	Bedroom 2	Bathroom 2	Bedroom 3	Bedroom 4	Laundry	Unit Score
A																	
A-951	1	1.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
B																	
B-957A	2	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
B-957B	2	1.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
B-959A	3	2.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
B-959B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
B-959C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
C																	
C-965A	4	2.0	0	-	G	G	G	G	-	G	G	-	-	-	-	G	G
C-965B	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
C-965C	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G



Apt.Nbr.	Beds	Baths	HC	Sq. Ft.	Living Area/Hallway	Dining Area	Kitchen	Utility Closet	Bathroom (Half)	Bathroom 1	Bedroom 1	Bedroom 2	Bathroom 2	Bedroom 3	Bedroom 4	Laundry	Unit Score
----------	------	-------	----	---------	---------------------	-------------	---------	----------------	-----------------	------------	-----------	-----------	------------	-----------	-----------	---------	------------

C continued

C-965D	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
C-967A	4	2.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
C-967B	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
C-967C	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
C-967D	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
C-969A	4	2.0	0	-	G	-	G	G	-	G	G	-	-	-	-	-	G
C-969B	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
C-969C	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
C-969D	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
C-971A	4	2.0	0	-	G	-	G	G	-	G	F	-	-	-	-	G	G
C-971B	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
C-971C	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
C-971D	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G

D

D-977	2	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
-------	---	-----	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---



Apt.Nbr.	Beds	Baths	HC	Sq. Ft.	Living Area/Hallway	Dining Area	Kitchen	Utility Closet	Bathroom (Half)	Bathroom 1	Bedroom 1	Bedroom 2	Bathroom 2	Bedroom 3	Bedroom 4	Laundry	Unit Score
D continued																	
D-979A	3	2.0	0	-	G	-	G	G	-	G	G	-	-	-	-	-	G
D-979B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
D-979C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
E																	
E-993	1	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	-	G
E-995A	2	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	-	G
E-995B	2	1.0	0	-	-	-	-	-	-	G	F	-	-	-	-	-	G
F																	
F-946A	2	1.0	0	-	F	-	-	G	-	G	G	-	-	-	-	-	G
F-946B	2	1.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
F-948	1	1.0	0	-	F	-	G	G	-	G	G	-	-	-	-	-	G
G																	
G-934A	3	2.0	0	-	G	-	G	G	-	G	G	-	-	-	-	-	G
G-934B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
G-934C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G



Apt.Nbr.	Beds	Baths	HC	Sq. Ft.	Living Area/Hallway	Dining Area	Kitchen	Utility Closet	Bathroom (Half)	Bathroom 1	Bedroom 1	Bedroom 2	Bathroom 2	Bedroom 3	Bedroom 4	Laundry	Unit Score
----------	------	-------	----	---------	---------------------	-------------	---------	----------------	-----------------	------------	-----------	-----------	------------	-----------	-----------	---------	------------

G continued

G-936A	3	2.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
G-936B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
G-936C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
G-938A	3	2.0	0	-	G	-	-	G	-	G	G	-	-	-	-	G	G
G-938B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
G-938C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
G-940A	3	2.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
G-940B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
G-940C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G

H

H-908A	3	2.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
H-908B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
H-908C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
H-910A	3	2.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
H-910B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G



Apt.Nbr.	Beds	Baths	HC	Sq. Ft.	Living Area/Hallway	Dining Area	Kitchen	Utility Closet	Bathroom (Half)	Bathroom 1	Bedroom 1	Bedroom 2	Bathroom 2	Bedroom 3	Bedroom 4	Laundry	Unit Score
----------	------	-------	----	---------	---------------------	-------------	---------	----------------	-----------------	------------	-----------	-----------	------------	-----------	-----------	---------	------------

H continued

H-910C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
H-912A	2	1.0	0	-	G	-	G	G	-	-	-	-	-	-	-	G	G
H-912B	2	1.0	0	-	-	-	-	-	G	G	-	-	-	-	-	-	G
H-914	2	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
H-920A	2	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
H-920B	2	1.0	0	-	-	-	-	-	G	G	-	-	-	-	-	-	G
H-922	2	1.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
H-924A	3	2.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
H-924B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
H-924C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
H-926A	3	2.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
H-926B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
H-926C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
H-928	1	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G

I



Apt.Nbr.	Beds	Baths	HC	Sq. Ft.	Living Area/Hallway	Dining Area	Kitchen	Utility Closet	Bathroom (Half)	Bathroom 1	Bedroom 1	Bedroom 2	Bathroom 2	Bedroom 3	Bedroom 4	Laundry	Unit Score
----------	------	-------	----	---------	---------------------	-------------	---------	----------------	-----------------	------------	-----------	-----------	------------	-----------	-----------	---------	------------

I continued

I-903	1	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
I-905A	2	1.0	0	-	G	-	G	G	-	-	-	-	-	-	-	G	G
I-905B	2	1.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G

J

J-909A	4	2.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
J-909B	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
J-909C	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
J-909D	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
J-911A	4	2.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
J-911B	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
J-911C	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
J-911D	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
J-913A	4	2.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
J-913B	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
J-913C	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G



Apt.Nbr.	Beds	Baths	HC	Sq. Ft.	Living Area/Hallway	Dining Area	Kitchen	Utility Closet	Bathroom (Half)	Bathroom 1	Bedroom 1	Bedroom 2	Bathroom 2	Bedroom 3	Bedroom 4	Laundry	Unit Score
----------	------	-------	----	---------	---------------------	-------------	---------	----------------	-----------------	------------	-----------	-----------	------------	-----------	-----------	---------	------------

J continued

J-913D	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
J-915A	4	2.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
J-915B	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
J-915C	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
J-915D	4	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G

K

K-925	2	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
K-927A	3	2.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
K-927B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
K-927C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G

L

L-935A	3	2.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
L-935B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
L-935C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
L-937A	3	2.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G



Apt.Nbr.	Beds	Baths	HC	Sq. Ft.	Living Area/Hallway	Dining Area	Kitchen	Utility Closet	Bathroom (Half)	Bathroom 1	Bedroom 1	Bedroom 2	Bathroom 2	Bedroom 3	Bedroom 4	Laundry	Unit Score
----------	------	-------	----	---------	---------------------	-------------	---------	----------------	-----------------	------------	-----------	-----------	------------	-----------	-----------	---------	------------

L continued

L-937B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
L-937C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
L-939A	3	2.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
L-939B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
L-939C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
L-941A	3	2.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
L-941B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
L-941C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G

M

M-550A	3	2.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
M-550B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
M-550C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
M-552	2	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G

N

N-544	1	1.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
-------	---	-----	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

O



Apt.Nbr.	Beds	Baths	HC	Sq. Ft.	Living Area/Hallway	Dining Area	Kitchen	Utility Closet	Bathroom (Half)	Bathroom 1	Bedroom 1	Bedroom 2	Bathroom 2	Bedroom 3	Bedroom 4	Laundry	Unit Score
----------	------	-------	----	---------	---------------------	-------------	---------	----------------	-----------------	------------	-----------	-----------	------------	-----------	-----------	---------	------------

O continued

O-518A	3	2.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
O-518B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
O-518C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
O-520A	3	2.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
O-520B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
O-520C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
O-522A	2	1.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
O-522B	2	1.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
O-524A	2	1.0	0	-	F	-	G	G	-	G	G	-	-	-	-	G	G
O-524B	2	1.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
O-530	2	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
O-532A	2	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
O-532B	2	1.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
O-534A	3	2.0	0	-	F	-	G	G	-	-	F	-	-	-	-	G	G
O-534B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G



Apt.Nbr.	Beds	Baths	HC	Sq. Ft.	Living Area/Hallway	Dining Area	Kitchen	Utility Closet	Bathroom (Half)	Bathroom 1	Bedroom 1	Bedroom 2	Bathroom 2	Bedroom 3	Bedroom 4	Laundry	Unit Score
O continued																	
O-534C	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
O-536A	3	2.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
O-536B	3	2.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
O-536C	3	2.0	0	-	-	-	-	-	-	-	-	-	-	-	-	-	-
O-538	1	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
P																	
P-510A	2	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G
P-510B	2	1.0	0	-	-	-	-	-	-	G	G	-	-	-	-	-	G
P-512	1	1.0	0	-	G	-	G	G	-	G	G	-	-	-	-	G	G



Inspection Photos

Site

Grounds



8

Site - Grounds - Lighting/Site - May 10 2023 3:45PM - S Franco



9

Site - Grounds - Lighting/Site - May 10 2023 3:46PM - S Franco



10

Site - Grounds - Lighting/Site - May 10 2023 3:48PM - S Franco



11

Site - Grounds - Dumpster Enclosure - May 10 2023 3:36PM - S Franco



12

Site - Grounds - Erosion - May 10 2023 3:42PM - S Franco



13

Site - Grounds - Erosion - May 10 2023 3:43PM - S Franco

A

Exterior Wall



14

A - Exterior Wall - Paint - May 8 2023 9:21AM - S Franco

Inspection Photos (Continued)

HVAC



41

A - HVAC - HVAC System - May 8 2023
10:39AM - S Franco

Rooftop



15

A - Rooftop - General Location - May 8
2023 10:39AM - S Franco

A: Unit A-951

Utility Closet



46

A Unit A-951 - Utility Closet - Water
Heater - May 9 2023 9:29AM - S Franco



47

A Unit A-951 - Utility Closet - HVAC -
May 9 2023 9:29AM - S Franco

Inspection Photos (Continued)

Bathroom 1



48

A Unit A-951 - Bathroom 1 - GFCI/AFCI
- May 9 2023 9:21AM - S Franco



50

A Unit A-951 - Bathroom 1 - General
Location - May 9 2023 9:19AM - S
Franco



51

A Unit A-951 - Bathroom 1 - General
Location - May 9 2023 9:19AM - S
Franco

Laundry



49

A Unit A-951 - Laundry - Flooring - May
9 2023 9:28AM - S Franco

Kitchen



52

A Unit A-951 - Kitchen - General
Location - May 9 2023 9:24AM - S
Franco

Inspection Photos (Continued)

B

General Building



1

B - General Building - General Building - May 9 2023 9:32AM - S Franco

Exterior Wall



16

B - Exterior Wall - Paint - May 8 2023 9:25AM - S Franco

HVAC



42

B - HVAC - HVAC System - May 8 2023 10:41AM - S Franco

Inspection Photos (Continued)

Rooftop



17

B - Rooftop - General Location - May 8 2023 10:40AM - S Franco

B: Unit B-957A

Living Area/Hallway



53

B Unit B-957A - Living Area/Hallway - Service Panel - May 9 2023 9:36AM - S Franco

Bedroom 1



54

B Unit B-957A - Bedroom 1 - Flooring - May 9 2023 9:44AM - S Franco

Inspection Photos (Continued)

Bathroom 1



55

B Unit B-957A - Bathroom 1 - General
Location - May 9 2023 9:46AM - S
Franco



56

B Unit B-957A - Bathroom 1 - General
Location - May 9 2023 9:46AM - S
Franco

Kitchen



57

B Unit B-957A - Kitchen - General
Location - May 9 2023 9:39AM - S
Franco



58

B Unit B-957A - Kitchen - General
Location - May 9 2023 9:39AM - S
Franco

Utility Closet



59

B Unit B-957A - Utility Closet - General
Location - May 9 2023 9:42AM - S
Franco

Inspection Photos (Continued)

B: Unit B-957B

Bathroom 1



60

B Unit B-957B - Bathroom 1 - Toilet -
May 9 2023 9:49AM - S Franco



61

B Unit B-957B - Bathroom 1 -
Bathtub/Shower - May 9 2023 9:50AM -
S Franco



63

B Unit B-957B - Bathroom 1 - General
Location - May 9 2023 9:48AM - S
Franco

Bedroom 1



62

B Unit B-957B - Bedroom 1 - Flooring -
May 9 2023 9:48AM - S Franco

B: Unit B-959A

Living Area/Hallway



64

B Unit B-959A - Living Area/Hallway -
Service Panel - May 9 2023 9:52AM - S
Franco

Inspection Photos (Continued)

Utility Closet



65

B Unit B-959A - Utility Closet - HVAC -
May 9 2023 9:55AM - S Franco

Kitchen



66

B Unit B-959A - Kitchen - General
Location - May 9 2023 9:53AM - S
Franco

Laundry



67

B Unit B-959A - Laundry - General
Location - May 9 2023 10:05AM - S
Franco

Inspection Photos (Continued)

B: Unit B-959B

Bathroom 1



68

B Unit B-959B - Bathroom 1 - General
Location - May 9 2023 10:01AM - S
Franco



69

B Unit B-959B - Bathroom 1 - General
Location - May 9 2023 10:01AM - S
Franco

C

Exterior Wall



18

C - Exterior Wall - Paint - May 8 2023
10:51AM - S Franco

Rooftop



19

C - Rooftop - Roofing, Asphalt Shingle -
May 8 2023 10:45AM - S Franco

Inspection Photos (Continued)

HVAC



43

C - HVAC - HVAC System - May 8 2023
10:47AM - S Franco

C: Unit C-965A

Kitchen



70

C Unit C-965A - Kitchen - General
Location - May 9 2023 10:08AM - S
Franco

C: Unit C-965C

Bathroom 1



71

C Unit C-965C - Bathroom 1 - Lighting
Fixture (Interior) - May 9 2023 10:16AM -
S Franco

Inspection Photos (Continued)

C: Unit C-967A

Bathroom 1



72

C Unit C-967A - Bathroom 1 - Lighting Fixture (Interior) - May 9 2023 10:31AM - S Franco

C: Unit C-969A

Bathroom 1



73

C Unit C-969A - Bathroom 1 - Sink and Faucet - May 9 2023 10:59AM - S Franco

C: Unit C-971A

Bedroom 1



74

C Unit C-971A - Bedroom 1 - Flooring - May 9 2023 10:45AM - S Franco

Inspection Photos (Continued)

C: Unit C-971B

Bathroom 1



75

C Unit C-971B - Bathroom 1 - Vanity -
May 9 2023 10:48AM - S Franco

D

Rooftop



20

D - Rooftop - Roofing, Asphalt Shingle -
May 8 2023 10:55AM - S Franco

Windows



21

D - Windows - Window - May 8 2023
10:54AM - S Franco

Inspection Photos (Continued)

D: Unit D-977

Kitchen



76

D Unit D-977 - Kitchen - Cabinets - May 9 2023 11:09AM - S Franco

E

Rooftop



22

E - Rooftop - Roofing, Asphalt Shingle - May 8 2023 10:57AM - S Franco

Windows



23

E - Windows - Window - May 8 2023 10:58AM - S Franco

Inspection Photos (Continued)

E: Unit E-995B

Bedroom 1



27

E Unit E-995B - Bedroom 1 - Flooring -
May 9 2023 11:42AM - S Franco

F

Exterior Wall



24

F - Exterior Wall - Siding, Wood - May 8
2023 11:03AM - S Franco

Rooftop



25

F - Rooftop - Roofing, Asphalt Shingle -
May 8 2023 11:00AM - S Franco

Inspection Photos (Continued)

F: Unit F-946A

Living Area/Hallway



78

F Unit F-946A - Living Area/Hallway -
Door, Entry - May 9 2023 1:35PM - S
Franco

F: Unit F-948

Living Area/Hallway



79

F Unit F-948 - Living Area/Hallway -
Door, Entry - May 9 2023 1:28PM - S
Franco

G

Exterior Wall



26

G - Exterior Wall - Paint - May 8 2023
11:06AM - S Franco

Inspection Photos (Continued)

Rooftop



27

G - Rooftop - Roofing, Asphalt Shingle -
May 8 2023 11:09AM - S Franco

H

Exterior Wall



28

H - Exterior Wall - Paint - May 8 2023
11:12AM - S Franco

Rooftop



29

H - Rooftop - Roofing, Asphalt Shingle -
May 8 2023 11:14AM - S Franco

Inspection Photos (Continued)

Windows



30

H - Windows - Window - May 8 2023
11:14AM - S Franco

H: Unit H-908A

Living Area/Hallway



80

H Unit H-908A - Living Area/Hallway -
Door, Entry - May 10 2023 10:27AM - S
Franco

H: Unit H-908B

Bathroom 1



81

H Unit H-908B - Bathroom 1 -
Bathtub/Shower - May 10 2023 10:36AM
- S Franco

Inspection Photos (Continued)

H: Unit H-914

Kitchen



82

H Unit H-914 - Kitchen - Range
Hood/Vent Fan - May 10 2023 9:49AM -
S Franco

Laundry



83

H Unit H-914 - Laundry - General
Location - May 10 2023 9:47AM - S
Franco

H: Unit H-920A

Kitchen



84

H Unit H-920A - Kitchen - Range
Hood/Vent Fan - May 10 2023 10:07AM -
S Franco

Inspection Photos (Continued)

Laundry



85

H Unit H-920A - Laundry - General Location - May 10 2023 10:05AM - S Franco




86

H Unit H-920A - Laundry - General Location - May 10 2023 10:05AM - S Franco

H: Unit H-920B

Bedroom 1



87

H Unit H-920B - Bedroom 1 - Flooring - May 10 2023 10:10AM - S Franco

H: Unit H-922

Living Area/Hallway



88

H Unit H-922 - Living Area/Hallway - Door, Entry - May 10 2023 9:38AM - S Franco

Inspection Photos (Continued)

H: Unit H-924A

Living Area/Hallway



89

H Unit H-924A - Living Area/Hallway - Door, Entry - May 10 2023 9:14AM - S Franco

Kitchen



90

H Unit H-924A - Kitchen - Dishwasher - May 10 2023 9:19AM - S Franco



91

H Unit H-924A - Kitchen - Stove/Range - May 10 2023 9:19AM - S Franco



92

H Unit H-924A - Kitchen - Range Hood/Vent Fan - May 10 2023 9:19AM - S Franco

Bathroom 1



93

H Unit H-924A - Bathroom 1 - Toilet - May 10 2023 9:22AM - S Franco

Inspection Photos (Continued)

H: Unit H-924C

Bathroom 1



94

H Unit H-924C - Bathroom 1 - Sink and Faucet - May 10 2023 9:27AM - S Franco

H: Unit H-926A

Kitchen



95

H Unit H-926A - Kitchen - Sink and Faucet - May 10 2023 9:31AM - S Franco

H: Unit H-926B

Bathroom 1



96

H Unit H-926B - Bathroom 1 - Sink and Faucet - May 10 2023 9:33AM - S Franco



97

H Unit H-926B - Bathroom 1 - Lighting Fixture (Interior) - May 10 2023 9:34AM - S Franco



98

H Unit H-926B - Bathroom 1 - Bathtub/Shower - May 10 2023 9:34AM - S Franco

Inspection Photos (Continued)

I

Rooftop



31

I - Rooftop - Roofing, Asphalt Shingle -
May 8 2023 11:16AM - S Franco

J

General Building



2

J - General Building - General Building -
May 8 2023 11:32AM - S Franco

Windows




32

J - Windows - Window - May 8 2023
1:19PM - S Franco

Inspection Photos (Continued)

J: Unit J-909A

Living Area/Hallway



99

J Unit J-909A - Living Area/Hallway - Door, Entry - May 10 2023 10:59AM - S Franco



100

J Unit J-909A - Living Area/Hallway - Flooring - May 10 2023 11:00AM - S Franco

J: Unit J-909B

Bedroom 1



101

J Unit J-909B - Bedroom 1 - Lighting Fixture (Interior) - May 10 2023 11:06AM - S Franco

J: Unit J-909C

Bedroom 1



102

J Unit J-909C - Bedroom 1 - Lighting Fixture (Interior) - May 10 2023 11:07AM - S Franco

Inspection Photos (Continued)

J: Unit J-909D

Bedroom 1




103

J Unit J-909D - Bedroom 1 - Lighting
Fixture (Interior) - May 10 2023 11:09AM
- S Franco

J: Unit J-911A

Living Area/Hallway



104

J Unit J-911A - Living Area/Hallway -
Door, Entry - May 10 2023 11:12AM - S
Franco

Kitchen



105

J Unit J-911A - Kitchen - Flooring - May
10 2023 11:14AM - S Franco

Inspection Photos (Continued)

J: Unit J-915A

Living Area/Hallway



106

J Unit J-915A - Living Area/Hallway -
Door, Entry - May 10 2023 11:24AM - S
Franco

K

General Building



3

K - General Building - General Building -
May 8 2023 1:27PM - S Franco

Exterior Wall



33

K - Exterior Wall - Paint - May 8 2023
1:27PM - S Franco

Inspection Photos (Continued)

K: Unit K-927A

Kitchen



107

K Unit K-927A - Kitchen - Stove/Range -
May 10 2023 1:34PM - S Franco

K: Unit K-927C

Bedroom 1



108

K Unit K-927C - Bedroom 1 - Flooring -
May 10 2023 1:38PM - S Franco

L

General Building



4

L - General Building - General Building -
May 8 2023 1:31PM - S Franco

Inspection Photos (Continued)

Exterior Wall



34

L - Exterior Wall - Paint - May 8 2023
2:04PM - S Franco

Windows



35

L - Windows - Window - May 8 2023
2:03PM - S Franco

Electrical System



44

L - Electrical System - Electric Meter -
May 8 2023 1:32PM - S Franco

Inspection Photos (Continued)

L: Unit L-935A

Living Area/Hallway



109

L Unit L-935A - Living Area/Hallway -
Flooring - May 10 2023 1:45PM - S
Franco

L: Unit L-941A

Living Area/Hallway



110

L Unit L-941A - Living Area/Hallway -
Flooring - May 10 2023 2:10PM - S
Franco

Kitchen



111

L Unit L-941A - Kitchen - Flooring - May
10 2023 2:09PM - S Franco

Inspection Photos (Continued)

M

General Building



5

M - General Building - General Building - May 8 2023 2:08PM - S Franco

M: Unit M-550B

Bathroom 1



112

M Unit M-550B - Bathroom 1 - Lighting Fixture (Interior) - May 10 2023 2:45PM - S Franco

N

General Building



6

N - General Building - General Building - May 8 2023 2:18PM - S Franco

Inspection Photos (Continued)

Exterior Wall



36

N - Exterior Wall - Paint - May 8 2023
2:21PM - S Franco

O

Exterior Wall



37

O - Exterior Wall - Paint - May 8 2023
2:31PM - S Franco

O: Unit O-518A

Utility Closet



113

O Unit O-518A - Utility Closet - Lighting
Fixture (Interior) - May 11 2023 10:11AM
- S Franco

Inspection Photos (Continued)

O: Unit O-532A

Living Area/Hallway



114

O Unit O-532A - Living Area/Hallway -
Lighting Fixture (Interior) - May 11 2023
9:46AM - S Franco

O: Unit O-536A

Kitchen



115

O Unit O-536A - Kitchen - Dishwasher -
May 11 2023 9:39AM - S Franco

O: Unit O-536B

Bathroom 1



116

O Unit O-536B - Bathroom 1 -
Bathtub/Shower - May 11 2023 9:43AM -
S Franco

Inspection Photos (Continued)

P

Exterior Wall



38

P - Exterior Wall - Paint - May 8 2023
2:40PM - S Franco

Entry Door



39

P - Entry Door - Door, Entry - May 8
2023 2:43PM - S Franco

Clubhouse

General Building



Z

Clubhouse - General Building - General
Building - May 8 2023 2:46PM - S
Franco

Inspection Photos (Continued)

Exterior Wall



40

Clubhouse - Exterior Wall - Paint - May 8 2023 2:49PM - S Franco

Fire Safety



45

Clubhouse - Fire Safety - Fire Pump - May 11 2023 10:32AM - S Franco

Notes and Comments

Site

Grounds

Note Nbr	Location - Item	Notes/Comments
1	Grounds Lighting/Site	Lighting is not Sufficient for property
2	Grounds Lawn Sprinkler System	Irrigation system does not have a water supply

A: Unit A-951

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
10	Living Area/Hallway Door, Entry	Needs paint
11	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
12	Kitchen Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
13	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
14	Laundry Flooring	Ceramic tile

B

Exterior Wall

Note Nbr	Location - Item	Notes/Comments
3	Exterior Wall Paint	Paint oxidation

B: Unit B-957A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
15	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
16	Kitchen Flooring	Vinyl

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
17	Bathroom 1 Flooring	Ceramic tile

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
18	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
19	Laundry Flooring	Ceramic tile

B: Unit B-957B

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
20	Bedroom 1 Flooring	Carpet

B: Unit B-959A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
21	Living Area/Hallway Flooring	Carpet

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
22	Bathroom 1 Flooring	Ceramic tile

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
23	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
24	Laundry Flooring	Ceramic tile

B: Unit B-959B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
25	Bathroom 1 Flooring	Ceramic tile

Notes and Comments (Continued)

C: Unit C-965A

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
26	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
27	Laundry Flooring	Ceramic tile

C: Unit C-965B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
28	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
29	Bedroom 1 Flooring	Carpet

C: Unit C-965C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
30	Bathroom 1 Flooring	Ceramic tile

C: Unit C-965D

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
31	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
32	Bedroom 1 Flooring	Carpet

C: Unit C-967A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
33	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
34	Kitchen Flooring	Vinyl

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
35	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
36	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
37	Laundry Flooring	Ceramic tiles

C: Unit C-967B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
38	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
39	Bedroom 1 Flooring	Carpet

C: Unit C-967C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
40	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
41	Bedroom 1 Flooring	Carpet

C: Unit C-967D

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
42	Bathroom 1 Flooring	Ceramic tiles

Notes and Comments (Continued)

Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
43	Bedroom 1 Flooring	Carpet
C: Unit C-969A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
44	Living Area/Hallway Door, Entry	Needs paint
45	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
46	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
47	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
48	Bedroom 1 Flooring	Carpet
C: Unit C-969B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
49	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
50	Bedroom 1 Flooring	Carpet
C: Unit C-969C		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
51	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
52	Bedroom 1 Flooring	Carpet
C: Unit C-969D		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
53	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
54	Bedroom 1 Flooring	Carpet
C: Unit C-971A		
Kitchen		
Note Nbr	Location - Item	Notes/Comments
55	Kitchen Flooring	Vinyl
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
56	Bathroom 1 Flooring	Ceramic tiles
Laundry		
Note Nbr	Location - Item	Notes/Comments
57	Laundry Flooring	Ceramic tiles
C: Unit C-971B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
58	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
59	Bedroom 1 Flooring	Carpet
C: Unit C-971C		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
60	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
61	Bedroom 1 Flooring	Carpet

Notes and Comments (Continued)

C: Unit C-971D

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
62	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
63	Bedroom 1 Flooring	Carpet

D

Exterior Wall

Note Nbr	Location - Item	Notes/Comments
4	Exterior Wall Paint	Paint oxidation

D: Unit D-977

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
64	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
65	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
66	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
67	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
68	Laundry Flooring	Ceramic tiles

D: Unit D-979A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
69	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
70	Kitchen Flooring	Vinyl tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
71	Bedroom 1 Flooring	Carpet

D: Unit D-979B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
72	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
73	Bedroom 1 Flooring	Carpet

D: Unit D-979C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
74	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
75	Bedroom 1 Flooring	Carpet

E: Unit E-993

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
76	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
77	Kitchen Flooring	Vinyl

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
78	Bathroom 1 Flooring	Ceramic tiles

Notes and Comments (Continued)

Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
79	Bedroom 1 Flooring	Carpet
E: Unit E-995A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
80	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
81	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
82	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
83	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
84	Laundry Flooring	Ceramic tiles
E: Unit E-995B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
85	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
86	Bedroom 1 Flooring	Carpet
F		
Exterior Wall		
Note Nbr	Location - Item	Notes/Comments
5	Exterior Wall Siding, Wood	Stained
F: Unit F-946A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
87	Living Area/Hallway Door, Entry	Needs paint
88	Living Area/Hallway Flooring	Carpet
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
89	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
90	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
91	Laundry Flooring	Ceramic tiles
F: Unit F-946B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
92	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
93	Bedroom 1 Flooring	Carpet
F: Unit F-948		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
94	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
95	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
96	Bathroom 1 Flooring	Ceramic

Notes and Comments (Continued)

Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
97	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
98	Laundry Flooring	Ceramic tiles
G: Unit G-934A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
99	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
100	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
101	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
102	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
103	Laundry Flooring	Ceramic tiles
G: Unit G-934B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
104	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
105	Bedroom 1 Flooring	Carpet
G: Unit G-934C		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
106	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
107	Bedroom 1 Flooring	Carpet
G: Unit G-936A		
Kitchen		
Note Nbr	Location - Item	Notes/Comments
108	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
109	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
110	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
111	Laundry Flooring	Ceramic tiles
G: Unit G-936B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
112	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
113	Bedroom 1 Flooring	Carpet
G: Unit G-936C		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
114	Bathroom 1 Flooring	Ceramic tiles

Notes and Comments (Continued)

Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
115	Bedroom 1 Flooring	Carpet
G: Unit G-938A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
116	Living Area/Hallway Flooring	Carpet
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
117	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
118	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
119	Laundry Flooring	Ceramic tiles
G: Unit G-938B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
120	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
121	Bedroom 1 Flooring	Carpet
G: Unit G-938C		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
122	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
123	Bedroom 1 Flooring	Carpet
G: Unit G-940A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
124	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
125	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
126	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
127	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
128	Laundry Flooring	Ceramic tiles
G: Unit G-940B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
129	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
130	Bedroom 1 Flooring	Carpet
G: Unit G-940C		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
131	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
132	Bedroom 1 Flooring	Carpet

Notes and Comments (Continued)

H

Exterior Wall

Note Nbr	Location - Item	Notes/Comments
6	Exterior Wall Paint	Paint oxidation

H: Unit H-908A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
133	Living Area/Hallway Door, Entry	Needs paint

Kitchen

Note Nbr	Location - Item	Notes/Comments
134	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
135	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
136	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
137	Laundry Flooring	Ceramic tiles

H: Unit H-908B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
138	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
139	Bedroom 1 Flooring	Carpet

H: Unit H-908C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
140	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
141	Bedroom 1 Flooring	Carpet

H: Unit H-910A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
142	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
143	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
144	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
145	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
146	Laundry Flooring	Ceramic tiles

H: Unit H-910B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
147	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
148	Bedroom 1 Flooring	Carpet

H: Unit H-910C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
149	Bathroom 1 Flooring	Ceramic tiles

Notes and Comments (Continued)

Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
150	Bedroom 1 Flooring	Carpet
H: Unit H-912A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
151	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
152	Kitchen Flooring	Vinyl tiles
H: Unit H-912B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
153	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
154	Bedroom 1 Flooring	Carpet
H: Unit H-914		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
155	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
156	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
157	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
158	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
159	Laundry Flooring	Ceramic tiles
H: Unit H-920A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
160	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
161	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
162	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
163	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
164	Laundry Flooring	Ceramic tiles
H: Unit H-920B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
165	Bathroom 1 Flooring	Ceramic tiles
H: Unit H-922		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
166	Living Area/Hallway Door, Entry	Needs paint
167	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
168	Kitchen Flooring	Vinyl tiles

Notes and Comments (Continued)

Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
169	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
170	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
171	Laundry Flooring	Ceramic tiles
H: Unit H-924A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
172	Living Area/Hallway Door, Entry	Needs paint
173	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
174	Kitchen Door, Entry	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
175	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
176	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
177	Laundry Flooring	Ceramic tiles
H: Unit H-924B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
178	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
179	Bedroom 1 Flooring	Carpet
H: Unit H-924C		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
180	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
181	Bedroom 1 Flooring	Carpet
H: Unit H-926A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
182	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
183	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
184	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
185	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
186	Laundry Flooring	Ceramic tiles
H: Unit H-926B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
187	Bathroom 1 Flooring	Ceramic tiles

Notes and Comments (Continued)

Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
188	Bedroom 1 Flooring	Carpet
H: Unit H-926C		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
189	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
190	Bedroom 1 Flooring	Carpet
H: Unit H-928		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
191	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
192	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
193	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
194	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
195	Laundry Flooring	Ceramic tiles
I		
Exterior Wall		
Note Nbr	Location - Item	Notes/Comments
7	Exterior Wall Paint	Oxidation
I: Unit I-903		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
196	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
197	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
198	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
199	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
200	Laundry Flooring	Ceramic tiles
I: Unit I-905A		
General Unit		
Note Nbr	Location - Item	Notes/Comments
201	General Unit General Unit	Did inspect due to resident being sick
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
202	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
203	Kitchen Flooring	Vinyl tiles
Laundry		
Note Nbr	Location - Item	Notes/Comments
204	Laundry Flooring	Ceramic tiles

Notes and Comments (Continued)

I: Unit I-905B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
205	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
206	Bedroom 1 Flooring	Carpet

J: Unit J-909A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
207	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
208	Kitchen Flooring	Ceramic tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
209	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
210	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
211	Laundry Flooring	Ceramic tiles

J: Unit J-909B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
212	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
213	Bedroom 1 Flooring	Carpet

J: Unit J-909C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
214	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
215	Bedroom 1 Flooring	Carpet

J: Unit J-909D

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
216	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
217	Bedroom 1 Flooring	Carpet

J: Unit J-911A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
218	Living Area/Hallway Door, Entry	Needs paint
219	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
220	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
221	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
222	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
223	Laundry Flooring	Ceramic tiles

Notes and Comments (Continued)

J: Unit J-911B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
224	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
225	Bedroom 1 Flooring	Carpet

J: Unit J-911C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
226	Bathroom 1 Flooring	Carpet

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
227	Bedroom 1 Flooring	Carpet

J: Unit J-911D

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
228	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
229	Bedroom 1 Flooring	Carpet

J: Unit J-913A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
230	Living Area/Hallway Door, Entry	Needs paint
231	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
232	Kitchen Flooring	Vinyl tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
233	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
234	Laundry Flooring	Ceramic tiles

J: Unit J-913B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
235	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
236	Bedroom 1 Flooring	Carpet

J: Unit J-913C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
237	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
238	Bedroom 1 Flooring	Carpet

J: Unit J-913D

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
239	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
240	Bedroom 1 Flooring	Carpet

J: Unit J-915A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
241	Living Area/Hallway Door, Entry	Needs paint
242	Living Area/Hallway Flooring	Carpet

Notes and Comments (Continued)

Kitchen		
Note Nbr	Location - Item	Notes/Comments
243	Kitchen Flooring	Vinyl tiles
Laundry		
Note Nbr	Location - Item	Notes/Comments
244	Laundry Flooring	Ceramic tiles
J: Unit J-915B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
245	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
246	Bedroom 1 Flooring	Carpet
J: Unit J-915C		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
247	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
248	Bedroom 1 Flooring	Carpet
J: Unit J-915D		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
249	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
250	Bedroom 1 Flooring	Carpet
K: Unit K-925		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
251	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
252	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
253	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
254	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
255	Laundry Flooring	Ceramic tiles
K: Unit K-927A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
256	Living Area/Hallway Door, Entry	Needs paint
257	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
258	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
259	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
260	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
261	Laundry Flooring	Ceramic tiles

Notes and Comments (Continued)

K: Unit K-927B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
262	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
263	Bedroom 1 Flooring	Carpet

K: Unit K-927C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
264	Bathroom 1 Flooring	Ceramic tiles

L

Exterior Wall

Note Nbr	Location - Item	Notes/Comments
8	Exterior Wall Paint	Oxidation

L: Unit L-935A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
265	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
266	Kitchen Flooring	Ceramic tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
267	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
268	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
269	Laundry Flooring	Ceramic tiles

L: Unit L-935B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
270	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
271	Bedroom 1 Flooring	Carpet

L: Unit L-935C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
272	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
273	Bedroom 1 Flooring	Carpet

L: Unit L-937A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
274	Living Area/Hallway Door, Entry	Needs paint
275	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
276	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
277	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
278	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
279	Laundry Flooring	Ceramic tiles

Notes and Comments (Continued)

L: Unit L-937B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
280	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
281	Bedroom 1 Flooring	Carpet

L: Unit L-937C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
282	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
283	Bedroom 1 Flooring	Carpet

L: Unit L-939A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
284	Living Area/Hallway Door, Entry	Needs paint
285	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
286	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
287	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
288	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
289	Laundry Flooring	Ceramic tiles

L: Unit L-939B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
290	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
291	Bedroom 1 Flooring	Carpet

L: Unit L-939C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
292	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
293	Bedroom 1 Flooring	Carpet

L: Unit L-941A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
294	Living Area/Hallway Door, Entry	Needs paint
295	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
296	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
297	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
298	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
299	Laundry Flooring	Ceramic tiles

Notes and Comments (Continued)

L: Unit L-941B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
300	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
301	Bedroom 1 Flooring	Carpet

L: Unit L-941C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
302	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
303	Bedroom 1 Flooring	Carpet

M: Unit M-550A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
304	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
305	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
306	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
307	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
308	Laundry Flooring	Ceramic tiles

M: Unit M-550B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
309	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
310	Bedroom 1 Flooring	Carpet

M: Unit M-550C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
311	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
312	Bedroom 1 Flooring	Carpet

M: Unit M-552

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
313	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
314	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
315	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
316	Bedroom 1 Flooring	Ceramic tiles

Laundry

Note Nbr	Location - Item	Notes/Comments
317	Laundry Flooring	Ceramic tiles

Notes and Comments (Continued)

N: Unit N-544

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
318	Living Area/Hallway Door, Entry	Needs paint
319	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
320	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
321	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
322	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
323	Laundry Flooring	Ceramic tiles

O

Exterior Wall

Note Nbr	Location - Item	Notes/Comments
9	Exterior Wall Paint	Oxidation

O: Unit O-518A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
324	Living Area/Hallway Door, Entry	Needs paint
325	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
326	Kitchen Flooring	Vinyl tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
327	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
328	Laundry Flooring	Ceramic tiles

O: Unit O-518B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
329	Bathroom 1 Flooring	Ceramic tiles

O: Unit O-518C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
330	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
331	Bedroom 1 Flooring	Carpet

O: Unit O-520A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
332	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
333	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
334	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
335	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
336	Laundry Flooring	Ceramic tiles

Notes and Comments (Continued)

O: Unit O-520B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
337	Bathroom 1 Flooring	Ceramic tiles

O: Unit O-520C

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
338	Bathroom 1 Flooring	Ceramic tiles

O: Unit O-522A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
339	Living Area/Hallway Door, Entry	Needs paint
340	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
341	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
342	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
343	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
344	Laundry Flooring	Ceramic tiles

O: Unit O-522B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
345	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
346	Bedroom 1 Flooring	Carpet

O: Unit O-524A

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
347	Living Area/Hallway Door, Entry	Needs paint
348	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
349	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
350	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
351	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
352	Laundry Flooring	Ceramic tiles

O: Unit O-524B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
353	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
354	Bedroom 1 Flooring	Carpet

O: Unit O-530

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
355	Living Area/Hallway Flooring	Carpet

Notes and Comments (Continued)

Kitchen		
Note Nbr	Location - Item	Notes/Comments
356	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
357	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
358	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
359	Laundry Flooring	Ceramic tiles
O: Unit O-532A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
360	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
361	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
362	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
363	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
364	Laundry Flooring	Ceramic tiles
O: Unit O-532B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
365	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
366	Bedroom 1 Flooring	Carpet
O: Unit O-534A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
367	Living Area/Hallway Door, Entry	Needs paint
368	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
369	Kitchen Flooring	80
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
370	Bedroom 1 Flooring	Ceramic tiles
Laundry		
Note Nbr	Location - Item	Notes/Comments
371	Laundry Flooring	Ceramic tiles
O: Unit O-534B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
372	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
373	Bedroom 1 Flooring	Carpet
O: Unit O-534C		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
374	Bathroom 1 Flooring	Ceramic tiles

Notes and Comments (Continued)

Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
375	Bedroom 1 Flooring	Carpet
O: Unit O-536A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
376	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
377	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
378	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
379	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
380	Laundry Flooring	Ceramic tiles
O: Unit O-536B		
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
381	Bathroom 1 Flooring	Ceramic tiles
382	Bathroom 1 Bathtub/Shower	Tub needs to be resurfaced
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
383	Bedroom 1 Flooring	Carpet
O: Unit O-538		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
384	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
385	Kitchen Flooring	Ceramic tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
386	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
387	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
388	Laundry Flooring	Ceramic tiles
P: Unit P-510A		
Living Area/Hallway		
Note Nbr	Location - Item	Notes/Comments
389	Living Area/Hallway Flooring	Carpet
Kitchen		
Note Nbr	Location - Item	Notes/Comments
390	Kitchen Flooring	Vinyl tiles
Bathroom 1		
Note Nbr	Location - Item	Notes/Comments
391	Bathroom 1 Flooring	Ceramic tiles
Bedroom 1		
Note Nbr	Location - Item	Notes/Comments
392	Bedroom 1 Flooring	Carpet
Laundry		
Note Nbr	Location - Item	Notes/Comments
393	Laundry Flooring	Ceramic tiles

Notes and Comments (Continued)

P: Unit P-510B

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
394	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
395	Bedroom 1 Flooring	Carpet

P: Unit P-512

Living Area/Hallway

Note Nbr	Location - Item	Notes/Comments
396	Living Area/Hallway Flooring	Carpet

Kitchen

Note Nbr	Location - Item	Notes/Comments
397	Kitchen Flooring	Vinyl tiles

Bathroom 1

Note Nbr	Location - Item	Notes/Comments
398	Bathroom 1 Flooring	Ceramic tiles

Bedroom 1

Note Nbr	Location - Item	Notes/Comments
399	Bedroom 1 Flooring	Carpet

Laundry

Note Nbr	Location - Item	Notes/Comments
400	Laundry Flooring	Ceramic tiles